

Test Report

TAIWAN MELAMINE PRODUCTS INDUSTRIAL CO., LTD.
NO. 11, LANE 3, SHUANG, CHENG STREET, TAIPEI 10453, TAIWAN

No. : CY/2007/50462
Date : 2007/05/23
Page : 1 of 3



The following sample(s) was/were submitted and identified by/on behalf of the client as :

Sample Description : SQUARE PLATE WITH BLACK BORDER
Style/Item No. : SP510L
Manufacturer/Vendor : TAIWAN MELAMINE PRODUCTS INDUSTRIAL CO., LTD.
Country of Origin : CHINA
Sample Receiving Date : 2007/05/14
Testing Period : 2007/05/14 TO 2007/05/23

=====
Test Result(s) : Please refer to next page(s).


Daniel Yeh, M.R. / Operation Manager
Signed for and on behalf of
SGS TAIWAN LTD.

Test Report

TAIWAN MELAMINE PRODUCTS INDUSTRIAL CO., LTD.
NO. 11, LANE 3, SHUANG, CHENG STREET, TAIPEI 10453, TAIWAN

No. : CY/2007/50462
Date : 2007/05/23
Page : 2 of 3



Test Result(s)

PART NAME NO.1 : WHITE PLATE

Test Item (s):	Unit	Method	MDL	Result
				No.1
Dishwasher test (1-5 cycle)	**	Place the samples into the rack of dishwasher, then add dishwasher detergent. Set the dishwasher for a normal of 110 minutes wash/rinse/dry cycles. Allow to proceed automatically through the complete cycle. Repeat the wash/rinse/dry cycles four times for a total of five cycles. Evaluate the tested specimens at the end of each wash/rinse/dry cycles if there are any defect. (wash / rinse / dry cycle: 65°C)	-	No noticeable aesthetic defect were found.

- Note :
1. mg/kg = ppm
 2. n.d. = Not Detected
 3. MDL = Method Detection Limit
 4. " - " = Not Regulated
 5. ** = Qualitative analysis (No Unit)

Test Report

TAIWAN MELAMINE PRODUCTS INDUSTRIAL CO., LTD.
NO. 11, LANE 3, SHUANG, CHENG STREET, TAIPEI 10453, TAIWAN

No. : CY/2007/50462
Date : 2007/05/23
Page : 3 of 3



** End of Report **